
















Hydrology of the Black Creek Watershed & Subbasins

Legend

-  Downstream Black Creek
-  Upstream Black Creek
-  Downstream Black Creek
-  Rail Trail Watershed
-  Subbasin Boundaries
-  Black Creek Streams
-  Wetlands
-  Lakes & Ponds
-  Rail Trail Staff Plate
-  Chodikee Gaging Location
-  NYSDEC Gaging Location
-  Slabsides
-  Rail Trail
-  Major Roads




Staff Plate
You Are Here



Staff Plate Installation on 5/26/06:
Creek Level was at 0.90 ft.
Very high water on 1/18/06 would
have been at 2.69 ft on the plate.
See what the level is now.

June 2006



Paul A. Rubin
HydroQuest
P.O. Box 387
Stone Ridge, N.Y. 12484
845-657-8111
hydroquest@yahoo.com

